

Six Sigma Certification Exam Questions with Answers

(Based on ASQ Black Belt BOK DMAIC sections)

CONTROL

1) A black belt and a green belt are assigned to an assessment project. They need to measure whether trainers' evaluation scores at various six sigma training locations are in control. The data is variable and a sample size is 45. Which control chart should they use?

- a) X Bar / S
- b) X Bar / R
- c) I-MR
- d) NP

The X Bar / S should be used when the data is variable and the sample is greater than 10.

2) At a six sigma certification exam a black belt candidate correctly identified that C chart should be used with attribute data when:

- a) Measuring defects with variable sample size
- b) Measuring defects with constant sample size
- c) Measuring defectives with variable sample size
- d) Measuring defectives with constant sample size

The C chart is used with attribute data to measure defects with constant sample size. Answer a) is incorrect as it describes U chart. Answers c) and d) refer to P and NP charts for defectives and NOT defects.

3) _____ system maximizes equipment effectiveness by using a preventative maintenance program throughout the life of the equipment.

- a) DFSS
- b) TPM
- c) SMED
- d) Fishbone


TPM or Total Productive Maintenance was pioneered by Toyota group. It ensures continued and uninterrupted performance by equipment in a production process. DFSS stands for Design for Six Sigma and has no direct relation to equipment maintenance. SMED refers to a series of techniques which shorten changeover time for production machinery. Fishbone is not a system, but a diagram.

4) Applying Western Electric rules to control charts, what is the correct interpretation for the this control chart?

Zone A Between 2σ from the centerline and the control limit (3σ)

Zone B Between 1σ and 2σ from the centerline

Zone C Within 1σ of the centerline



- a) Variation is due to common causes
- b) This is a multi-vari chart
- c) Process has dual stability
- d) Assignable causes seem to be present

Answer d) is correct as by the Western Electric rules if 2 out of 3 consecutive points fall beyond the 2σ limit (in zone A or beyond), on the same side of the centerline then presences of assignable causes can be inferred. Reference: http://en.wikipedia.org/wiki/Western_Electric_rules

5) Every six sigma practitioner credits _____ with inventing control charts.

- a) Edwards Deming
- b) Walter Shewhart
- c) Joseph Juran
- d) Bill Smith

Walter Shewhart invented control charts while working for Bell in 1920s. These charts are also referred as Shewhart charts.